Capital Fund Program - Five-Year Action Plan

Status: Approved Approved By: O'BRIEN, MAURA 02/28/2022

Part	Part I: Summary							
PHA Name: Northampton Housing Authority		Locality (City/County & State) X Original 5-Year Plan		Revised 5-Year Plan (Revision No:)		
PHA Number: MA026								
Α.	Development Number and Name	Work Statement for Year 1 2022	Work Statement for Year 2 2023	Work Statement for Year 3 2024	Work Statement for Year 4 2025	Work Statement for Year 5 2026		
	JOSEPH H MCDONALD HSE (MA026000001)	\$297,575.00	\$297,575.00	\$297,575.00	\$297,575.00	\$297,575.00		

Work Statement for Year 1

H MCDONALD HSE (MA026000001) Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 5 units MCD		\$297,575.00
Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 5 units MCD		
			\$21,939.00
Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances Florence heights 8 Units		\$15,005.00
Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances at MCD 8 units		\$15,005.00
Pumps(Non-Dwelling Construction - Mechanical (1480)-Central Boiler)	Florence Heights Circular Pumps Boiler		\$30,270.00
ew Siding(Dwelling Unit-Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Siding)	Florence Heights		\$136,196.00
McDonald (Dwelling Unit-Interior (1480)-Kitchen Cabinets)	McDonald House - 6 units of Cabinets		\$20,000.00
]	Appliances (Dwelling Unit-Interior (1480)-Appliances) Pumps(Non-Dwelling Construction - Mechanical (1480)-Central Boiler) w Siding(Dwelling Unit-Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Siding)	Appliances (Dwelling Unit-Interior (1480)-Appliances) Replace Appliances at MCD 8 units Pumps (Non-Dwelling Construction - Mechanical (1480)-Central Boiler) Florence Heights Circular Pumps Boiler w Siding (Dwelling Unit-Exterior (1480)-Siding, Non-Dwelling Exterior (1480)-Siding) Florence Heights	Appliances (Dwelling Unit-Interior (1480)-Appliances) Replace Appliances at MCD 8 units Pumps(Non-Dwelling Construction - Mechanical (1480)-Central Boiler) Florence Heights Circular Pumps Boiler w Siding(Dwelling Unit-Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Siding) Florence Heights

U.S. Department of Housing and Urban Development Office of Public and Indian Housing 2577-0274 02/28/2022

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)						
Work State	Work Statement for Year 1 2022						
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost			
ID0054	Emergency Boiler Replacement (Non-Dwelling Interior (1480)-Mechanical)	McDonald		\$59,160.00			
	Subtotal of Estimated Cost			\$297,575.00			

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cos
	JOSEPH H MCDONALD HSE (MA026000001)			\$297,575.00
ID0031	Repair Basement(Dwelling Unit-Exterior (1480)-Foundations)	Repair Basement water penetration Florence Heights (12 units)		\$30,000.00
ID0033	Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances Florence heights 17 Units		\$34,915.00
ID0034	Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances at MCD 17 units		\$34,915.00
ID0035	Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 5 units MCD		\$15,000.00
ID0036	Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 9 Units Florence Heights		\$33,514.00
ID0040	Security System(Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Call-for-Aid Systems)	Security System MCD Network Video Recorder MCD-7 floors-2 per floor-with 6 megapixels -2 external-		\$96,371.00

U.S. Department of Housing and Urban Development Office of Public and Indian Housing 2577-0274 02/28/2022

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)						
Work State	Work Statement for Year 2 2023						
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost			
ID0055	Copy of Install new Siding(Dwelling Unit-Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Siding)	Florence Heights		\$52,860.00			
	Subtotal of Estimated Cost			\$297,575.00			

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	JOSEPH H MCDONALD HSE (MA026000001)			\$297,575.00
ID0042	Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 9 Units Florence Heights		\$45,000.00
ID0043	Security System(Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Other)	Security System Florence Heights Network Video Recorder and 15 Exterior Cameras		\$92,000.00
ID0044	Screen & Balcony Doors(Dwelling Unit-Exterior (1480)-Exterior Doors)	Replace Screen Doors at MCD		\$45,000.00
ID0045	Repair Basement(Dwelling Unit-Exterior (1480)-Foundations)	Repair Basement water penetration Florence Heights (10 units)		\$51,175.00
ID0046	Pedestrian Paving (Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving)	Pedestrian Paving Florence Heights		\$64,400.00
	Subtotal of Estimated Cost			\$297,575.00

Part II: Supporting	Pages - Physical Need	s Work Statements (s)
---------------------	-----------------------	-----------------------

Work Statement for Year 4

Work Statement for Teal 4 2025							
Identifier	Development Number/Name	General Description of Major Work Categories Quantity		Estimated Cost			
	JOSEPH H MCDONALD HSE (MA026000001)			\$297,575.00			
ID0047	Flooring Replacement (Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace Flooring of 8 Units at McDonald House		\$32,090.00			
ID0048	Plumbing Stack Replacements(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Plumbing)	Replace the shared plumbing stacks in units at Florence Heights		\$100,000.00			
ID0049	Boiler Replacement (Non-Dwelling Construction - Mechanical (1480)-Central Boiler)	Boiler Replacement at Florence Heights		\$137,485.00			
ID0050	Flooring Replacement (Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement in 4 units at Florence Heights		\$28,000.00			
	Subtotal of Estimated Cost			\$297,575.00			

Work Statement for Year 5

Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
JOSEPH H MCDONALD HSE (MA026000001)			\$297,575.00
Repair Basement(Dwelling Unit-Exterior (1480)-Foundations)	Repair Basement water penetration Florence Heights (12 units)		\$36,161.00
Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 9 units Florence Heights		\$50,860.00
Repointing Bricks(Non-Dwelling Exterior (1480)-Tuck Pointing)	McDonald House- Repointing the Bricks		\$163,715.00
Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Striping)	Florence Heights Parking Stripes and Curb Painting		\$1,950.00
Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Striping)	MCD Parking Stripes and Curb Painting		\$1,335.00
Cabinet Replacement(Dwelling Unit-Interior (1480)-Kitchen Cabinets)	McDonald House- 14 unit cabinet Replacement		\$43,554.00
	JOSEPH H MCDONALD HSE (MA026000001) Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Repointing Bricks(Non-Dwelling Exterior (1480)-Tuck Pointing) Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Striping) Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Striping)	Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (12 units)	JOSEPH H MCDONALD HSE (MA026000001) Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (12 units) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Flooring Replacement 9 units Florence Heights Repointing Bricks(Non-Dwelling Exterior (1480)-Tuck Pointing) McDonald House-Repointing the Bricks Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Curb and Gutter, Dwelling Unit-Site Work (1480)-Striping) Florence Heights Parking Stripes and Curb Painting Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Curb and Gutter, Dwelling Unit-Site Work (1480)-Striping) MCD Parking Stripes and Curb Painting MCD Parking Stripes and Curb Painting MCD Parking Stripes and Curb Painting

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)							
Work Statement for Year 5 2026		2026						
Identifier	Development Number/Name		General Description of Major Work Categories	Quantity	Estimated Cost			
	Subtotal of Estimated Cost				\$297,575.00			