Capital Fund Program - Five-Year Action Plan

Status: Approved Approved Date: 03/03/2020 Approved By: CWIEKA, ROBERT 07/31/2017

Part	Part I: Summary						
PHA Name: Northampton Housing Authority		Locality (City/County & State) X Original 5-Year Plan		Revised 5-Year Plan (Revision No:)	
PHA Number: MA026							
Α.	Development Number and Name	Work Statement for Year 1 2020	Work Statement for Year 2 2021	Work Statement for Year 3 2022	Work Statement for Year 4 2023	Work Statement for Year 5 2024	
	JOSEPH H MCDONALD HSE (MA026000001)	\$232,090.00	\$232,090.00	\$232,090.00	\$232,090.00	\$232,090.00	

Part II: Su	Part II: Supporting Pages - Physical Needs Work Statements (s) Work Statement for Year 1 2020				
Work State					
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost	
	JOSEPH H MCDONALD HSE (MA026000001)			\$232,090.00	
ID0004	Elevator Replacement Phase two(Non-Dwelling Construction - Mechanical (1480)-Elevator)	Replace all Components of existing elevator at MCD phase two. second elevator		\$220,090.00	
ID0006	Replace elevator two Phase two(Contract Administration (1480)-Other Fees and Costs)	Architecture Engineer Design Phase two second elevator		\$12,000.00	
	Subtotal of Estimated Cost			\$232,090.00	

Work Statement for Year 2

Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
JOSEPH H MCDONALD HSE (MA026000001)			\$232,090.00
vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	Replace vanity and sinks 50 units at Florence Heights		\$20,000.00
Screen Doors(Dwelling Unit-Exterior (1480)-Exterior Doors)	Replace Screen Doors at Florence Heights		\$45,000.00
Repair Basement(Dwelling Unit-Exterior (1480)-Foundations)	Repair Basement water penetration Florence Heights (10 units)		\$51,175.00
LED Lighting (Non-Dwelling Interior (1480)-Electrical)	LED Lighting in common area MCD		\$35,915.00
Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 5 units MCD		\$15,000.00
Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 5 Units Florence Heights		\$17,330.00
	JOSEPH H MCDONALD HSE (MA026000001) vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks) Screen Doors(Dwelling Unit-Exterior (1480)-Exterior Doors) Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) LED Lighting (Non-Dwelling Interior (1480)-Electrical) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	JOSEPH H MCDONALD HSE (MA026000001) vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks) Replace vanity and sinks 50 units at Florence Heights Screen Doors(Dwelling Unit-Exterior (1480)-Exterior Doors) Replace Screen Doors at Florence Heights Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (10 units) LED Lighting (Non-Dwelling Interior (1480)-Electrical) LED Lighting in common area MCD	JOSEPH H MCDONALD HSE (MA026000001) vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks) Replace vanity and sinks 50 units at Florence Heights Sereen Doors (Dwelling Unit-Exterior (1480)-Exterior Doors) Replace Screen Doors at Florence Heights Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (10 units) LED Lighting (Non-Dwelling Interior (1480)-Electrical) LED Lighting in common area MCD Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Flooring Replacement 5 units MCD

Subtotal of Estimated Cost

Part II: Su	Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work State	Work Statement for Year 2 2021				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost	
ID0014	Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances at MCD 8 units		\$15,000.00	
ID0015	Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances Florence heights 8 Units		\$15,000.00	
ID0016	Pedestrian Paving (Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving)	Pedestrian Paving Florence Heights		\$17,670.00	

\$232,090.00

Work Statement for Year 3

Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
JOSEPH H MCDONALD HSE (MA026000001)			\$232,090.00
Repair Basement(Dwelling Unit-Exterior (1480)-Foundations)	Repair Basement water penetration Florence Heights (12 units)		\$36,161.00
vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	Replace vanity and sinks 60 units at MCD		\$25,000.00
Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 9 units Florence Heights		\$32,314.00
Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 5 units MCD		\$15,000.00
Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances Florence heights 8 Units		\$16,165.00
Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances at MCD 8 units		\$16,165.00
	JOSEPH H MCDONALD HSE (MA026000001) Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	JOSEPH H MCDONALD HSE (MA026000001) Repair Basement (Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (12 units) vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks) Replace vanity and sinks 60 units at MCD Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Flooring Replacement 9 units Florence Heights Flooring Replacement 5 units MCD Replace Appliances (Dwelling Unit-Interior (1480)-Appliances) Replace Appliances Florence heights 8 Units	JOSEPH H MCDONALD HSE (MA026000001) Repair Basement (Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (12 units) vanity and Sinks (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks) Replace vanity and sinks 60 units at MCD Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Flooring Replacement 9 units Florence Heights Flooring Replacement 5 units MCD Replace Appliances (Dwelling Unit-Interior (1480)-Appliances) Replace Appliances Florence heights 8 Units

Part II: Supporting Pages	- Physical Needs Work Statements (s)	
---------------------------	--------------------------------------	--

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0026	Circular Pumps(Non-Dwelling Construction - Mechanical (1480)-Central Boiler)	Florence Heights Circular Pumps Boiler		\$34,250.00
ID0027	Repointing Bricks(Non-Dwelling Exterior (1480)-Tuck Pointing)	Florence heights Repointing Bricks		\$53,750.00
ID0028	Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Curb and Gutter)	Florence Heights Parking Stripes and Curb Painting		\$1,950.00
ID0029	Parking Stripes and Curb Painting(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Striping)	MCD Parking Stripes and Curb Painting		\$1,335.00
	Subtotal of Estimated Cost			\$232,090.00

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cos
	JOSEPH H MCDONALD HSE (MA026000001)			\$232,090.00
ID0031	Repair Basement(Dwelling Unit-Exterior (1480)-Foundations)	Repair Basement water penetration Florence Heights (12 units)		\$30,000.00
ID0033	Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances Florence heights 17 Units		\$34,915.00
ID0034	Replace Appliances (Dwelling Unit-Interior (1480)-Appliances)	Replace Appliances at MCD 17 units		\$34,915.00
ID0035	Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 5 units MCD		\$15,000.00
ID0036	Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 9 Units Florence Heights		\$33,514.00
ID0040	Security System(Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Other)	Security System MCD Network Video Recorder MCD-7 floors-2 per floor-with 6 megapixels -2 external-		\$83,746.00

U.S. Department of Housing and Urban Development Office of Public and Indian Housing 2577-0274 07/31/2017

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4		2023			
Identifier	Development Number/Name		General Description of Major Work Categories	Quantity	Estimated Cost
	Subtotal of Estimated Cost				\$232,090.00

Work Statement for Year 5

Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cos
JOSEPH H MCDONALD HSE (MA026000001)			\$232,090.00
Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Flooring Replacement 9 Units Florence Heights		\$33,514.00
Security System(Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Other)	Security System Florence Heights Network Video Recorder and 15 Exterior Cameras		\$58,000.00
Screen & Balcony Doors(Dwelling Unit-Exterior (1480)-Exterior Doors)	Replace Screen Doors at MCD		\$45,000.00
Repair Basement(Dwelling Unit-Exterior (1480)-Foundations)	Repair Basement water penetration Florence Heights (10 units)		\$51,175.00
Pedestrian Paving (Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving)	Pedestrian Paving Florence Heights & MCDonald		\$44,401.00
Subtotal of Estimated Cost			\$232,090.00
	JOSEPH H MCDONALD HSE (MA026000001) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Security System(Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Other) Screen & Balcony Doors(Dwelling Unit-Exterior (1480)-Exterior Doors) Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Pedestrian Paving (Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving)	JOSEPH H MCDONALD HSE (MA026000001) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Security System(Dwelling Unit-Interior (1480)-Call-for-Aid Systems, Dwelling Unit-Interior (1480)-Other) Security System Florence Heights Network Video Recorder and 15 Exterior Cameras Screen & Balcony Doors(Dwelling Unit-Exterior (1480)-Exterior Doors) Replace Screen Doors at MCD Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (10 units) Pedestrian Paving (Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving) Pedestrian Paving Florence Heights & MCDonald	JOSEPH H MCDONALD HSE (MA026000001) Flooring Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine)) Security System(Dwelling Unit-Interior (1480)-Call-for-Aid Systems, Dwelling Unit-Interior (1480)-Other) Security System Florence Heights Network Video Recorder and 15 Exterior Cameras Screen & Balcony Doors(Dwelling Unit-Exterior (1480)-Exterior Doors) Replace Screen Doors at MCD Repair Basement(Dwelling Unit-Exterior (1480)-Foundations) Repair Basement water penetration Florence Heights (10 units) Pedestrian Paving (Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving) Pedestrian Paving Florence Heights & MCDonald